

7003.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura Implementation Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/7003-1.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

From which two parts is the Fully Qualified Domain Name (FQDN) composed, and in what order must they be configured?

- A. First the host name and then the domain name
- B. First the domain name and then the host name
- C. First the COTS server IP address and then the port number
- D. First the COTS server port number and then the IP address

Correct Answer: A

QUESTION 2

A technician has configured a new media gateway by connecting to the serial port for the MGC and entering network information for the card as well as the IP address for the Primary call server. When the MGC reboots, the faceplate displays UNRG. The Call Server console shows 'IPMG registration denied\\'.


What should be done to solve this problem?

- A. Ping from the MGC to the call server over the E-LAN
- B. Check to ensure the TLAN cable for the MGC is connected and active
- C. Check to ensure the IPMG has been configured on the call server
- D. Power cycle the MGC card to force it to register

Correct Answer: C

QUESTION 3

Click the Exhibit button.



A customer has deployed a Communication Server (CS) 1000RIs. 7x system at their site, and has asked that a swap using the Element Manager Phones tool on the two telephone sets shows in the Print-out be performed.


What should the customer be told regarding the request?

- A. These two telephones cannot be swapped because they do not have competitive TN types.
- B. These two telephones can be swapped because they are both assigned to TGAR 1.
- C. These two telephones can be swapped because they both have the same VCE Class of service.
- D. These two telephones cannot be swapped because they are not in the same Call Pickup group.

Correct Answer: A

QUESTION 4

Click the exhibit button During the installation the installation of a Communication Server 1000E RIs. 7x High Availability system for a customer, attempts to register an IP 1230 Desktop telephone with the system are unsuccessful. Network connectivity issues have already been ruled out, however a system configuration issue is suspected.



What is causing the problem?

- A. The virtual gateway application is not enabled.
- B. The proper firmware has not been uploaded for this telephone.
- C. The Line Terminal Proxy Server is not enabled for the node
- D. The Datagram Transport Layer Security (DTLS) Policy off.

Correct Answer: C

QUESTION 5

A technician is completing the configuration of a new IP node for a system. All files have been transferred and

synchronized, and `restart applications` is clicked for the selected servers.

What will this cause the system to do?

- A. Reboot the Linux Server running the signaling server.
- B. Restart the signaling server application on selected servers.
- C. Restart the application on selected servers.
- D. Restart Jboss and the Signaling Server applications on the selected servers.

Correct Answer: C

[Latest 7003.1 Dumps](#)

[7003.1 Practice Test](#)

[7003.1 Exam Questions](#)