

76940X^{Q&As}

Avaya Converged Platform Support

Pass Avaya 76940X Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/76940x.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- ⚙ **Instant Download** After Purchase
- ⚙ **100% Money Back** Guarantee
- ⚙ **365 Days** Free Update
- ⚙ **800,000+** Satisfied Customers



QUESTION 1

A junior support engineer has been told by the support manager that summary status information for the ACP 4200 can be found in the Dashlets.

Where would the engineer go to view this information?

- A. Login to Avaya Orchestrator\\'s ACP Configuration Wizard link.
- B. Login to Avaya Orchestrator\\'s Homepage.
- C. Login to the Management Server Console\\'s Desktop.
- D. Login to the Management Server Console\\'s ACP Configuration Wizard link.

Correct Answer: B

Reference: <https://downloads.avaya.com/css/P8/documents/101054950> (13)

QUESTION 2

A support engineer logs into the System Manager (SMGR) application on an ACP 4.0 system with the intention of checking VPFM warning messages for the VSP switch. The engineer is unable to see the VPFM link in SMGR.

What could be causing this Problem?

- A. The VPFM link was removed from SMGR as part of the upgrade of the system to ACP 4.0.
- B. The engineer\\'s SMGR account has insufficient access privileges to launch VPFM.
- C. The VPFM link has been renamed as Orchestrator in ACP 4.0.
- D. The engineer should connect to VPFM directly and not through SMGR.

Correct Answer: B

QUESTION 3

Which benefit does the available G450 Gateway provide to the ACP 4200 solution?

- A. IP to H.323 translation
- B. SIP to IP transition
- C. IP to POTS transition
- D. SIP to SIP negotiation

Correct Answer: B

QUESTION 4

As part of a routine weekly maintenance test for the ACP 4200, a support engineer has been instructed to verify that the vMotion VMKernels for all ESXi hosts are reachable from each other using pings. During the latest maintenance test, the engineer notices that some of the pings are failing.

Which potential impact would this have on the ACP 4200?

- A. There will be no impact on the ESXi hosts, but the VSPs may reboot periodically.
- B. vMotion may not work as expected.
- C. The ESXi hosts may not be reachable from vCenter Server appliance.
- D. The ESXi hosts may reboot periodically.

Correct Answer: C

QUESTION 5

A customer requires additional Avaya Aura applications to be added to the ACP 4200. This has been reviewed and approved by Avaya's ACP Product Management team. It has been determined that a new computer server is required to meet the expanded resource requirement.

Which three parts of the Lifecycle Workbook need to be updated to provide for the new requirements? (Choose three.)

- A. Contact Info
- B. ACP 4200 Solution RMU Elevation
- C. Serial Numbers
- D. Network Data
- E. QA Checklist

Correct Answer: ABC

QUESTION 6

You are receiving High Availability warnings in the vSphere client.

To resolve the issue, what would you try first?

- A. Stop and restart VMs.
- B. Ensure Storage Array is reachable from VSP.
- C. In the cluster, check cabling between server and storage array.
- D. Right-click each Host in the cluster and select Reconfigure for HA.

Correct Answer: B

QUESTION 7

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. The system has two pairs of ServerTech PDUs.

Which statement about the PDU firmware file describes the upgrade process that the engineer needs to follow?

- A. It will need to be uploaded to all 4 PDUs.
- B. It will need to be uploaded to each PDU Management Web Interface.
- C. It will need to be uploaded to one PDU. This PDU will then distribute the file to the remaining 3 PDUs.
- D. It will need to be uploaded to Orchestrator. Orchestrator will then distribute the file to the 4 PDUs.

Correct Answer: C

QUESTION 8

What is the first step in upgrading the VSP switches in an Avaya ACP 4200?

- A. Verify redundancy is active.
- B. Power down secondary device.
- C. Verify connectivity to NTP server.
- D. Disable Telnet access.

Correct Answer: A

Reference: <https://downloads.avaya.com/css/P8/documents/101054946> (61, important)

QUESTION 9

For the HP Server iLO interface, where is the default password located?

- A. Default Password is MAC Address
- B. LifeCycle Management Workbook
- C. HP Server Admin Guide
- D. Tag on server

Correct Answer: D

Reference: https://support.hpe.com/hpesc/public/docDisplay?docId=mmr_kc-0103124

QUESTION 10

Service warning alarms are being received by Orchestrator indicating that Port 27 on VSP 4850-1 is down.

How would a support engineer determine the equipment that is connected to this port?

- A. Network Diagram in the Lifecycle Workbook
- B. Switch Wiring tab in the Lifecycle Workbook
- C. ACP Installation Guide
- D. Physical inspection

Correct Answer: D

[Latest 76940X Dumps](#)

[76940X PDF Dumps](#)

[76940X Study Guide](#)