300-370$^{Q\&As}$

Troubleshooting Cisco Wireless Enterprise Networks

Pass Cisco 300-370 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.lead4pass.com/300-370.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Which three steps would a network engineer use to troubleshoot an AP join problem? (Choose three.)

A. Validate the STP configuration.

B. Verify the ping AP from the controller.

C. Verify the ping AP from the client.

D. Verify that the AP is getting an address from the DHCP server

E. Validate the SNMP configuration.

F. Verify the authentication configuration parameters.

Correct Answer: ABF

References:

QUESTION 2

Refer to the exhibit. Why did Client 00:25:84:61:92:7d not get a response from the RADIUS server?

A. The RADIUS server rejected the username that was provided by the client.

B. The shared-secret keys on the controller and on the RADIUS server do not match.

C. The wireless controller does not have IP connectivity to the RADIUS server.

D. The client and the RADIUS server did not agree on the EAP type so the RADIUS server dropped the packet.

Correct Answer: B

QUESTION 3

Which channel width is the maximum that can be obtained by bonding two 802.11ac subchannels according to US

regulations?

A. 160 MHz

B. 120 MHz

C. 84 MHz

D. 240 MHz

Correct Answer: A

To increase throughput, 802.11ac introduces two new channel widths. All 802.11ac devices are required to support 80 MHz channels, which doubles the size of the spectral channel over 802.11n. It further adds a 160 MHz channel option for

even higher speeds. Due to the limitations of finding contiguous 160 MHz spectrum, the standard allows for a 160 MHz channel to be either a single contiguous block or two noncontiguous 80 MHz channels.

References:

QUESTION 4

An engineer has received an alarm on a wireless LAN controller and is unsure of its meaning. The engineer attempted to ping the wireless LAN controller interfaces. Which troubleshooting methodology does this action demonstrate?

A. bottom-up

B. follow the path

C. shoot from the hip

D. top-down

E. divide and conquer

Correct Answer: E

QUESTION 5

An engineer is troubleshooting AP join issues on a wireless infrastructure. While gathering debugs, the engineer notices that one of the commands may generate an excessive amount of data on the console. Which command causes this to occur?

A. debug capwap detail enable

B. debug capwap errors enable

C. debug capwap info enable

D. debug capwap events enable

E. debug capwap packet enable

F. debug capwap payload enable

Correct Answer: B

Latest 300-370 Dumps   300-370 Practice Test   300-370 Braindumps

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.lead4pass.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: