![Leads4Pass logo]

500-920^{Q&As}

Cisco Data Center Unified Computing Infrastructure Troubleshooting (DCITUC)

Pass Cisco 500-920 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.leads4pass.com/500-920.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

The command show interface veth 705 is telling you that the bound interface is Ethernet 3/1/2

What is the location of the blade that has veth 705 associated to it?

A. Chassis 3, Slot 1

B. Chassis 3. Slot 2

C. There is not enough information

D. Chassis 1. Slot 2

Correct Answer: A

QUESTION 2

In order to create an Inband Profile for Cisco Integrated Management Controller (IMC) connectivity, what do you need to perform first?

A. Create a Management IP Pool, a MAC Address Pool, and a VLAN Pool

B. Create an IPMI Policy

C. Create a Service Profile

D. Create different VLANs, with different VLAN IDs

E. Create a Management IP Pool, a VLAN. and a VLAN Group

Correct Answer: C

QUESTION 3

What three options should be verified, when you are able to connect to Cisco UCS Manager, but unable to open a KVM session to a blade? (Choose three)

A. Verify TCP port 2068 is not blocked by an ACL or Firewall

B. Confirm the IP Address assigned to UCS Manager is the same as the KVM address

C. Verify the KVM IP Address is on the same ip subnet as the virtual machines

D. Confirm the KVM IP Address is added to the route table in Cisco UCS Manager

E. Confirm the IP Address assigned to the KVM is not a duplicate IP

F. Verify the KVM IP Address is on the same subnet as the Fabric Interconnect management address

Correct Answer: ADE

QUESTION 4

A Hard Drive (HDD) has been hot swapped in a UCS server blade, however, the UCS Manager GUI is not displaying updated metrics about the replacement drive. What action will be required to properly display updated metrics?

A. Remove and re-insert the server blade HDD controller mezzanine card

B. Reboot the Fabric Interconnects

C. Reboot the server.

D. Use the CLI, since HDD metrics cannot be displayed with the UCS Manager GUI

Correct Answer: A

QUESTION 5

Which command sequence is required to reset Cisco Integrated Management Controller (IMC) of a Cisco UCS Server?

A. connect cimc | reset | validate

B. scope cimc | reset | commit-buffer

C. connect cimc | reset | commit

D. scope cimc | reset | validate

Correct Answer: B