642-980^{Q&As}

Troubleshooting Cisco Data Center Unified Fabric

Pass Cisco 642-980 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.lead4pass.com/642-980.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Refer to the exhibit.

```
FSPF-3-HELLO_MISMATCH: %$VSAN <vsan-id>%$ Mismatch in Hello timer in the Hello packet on
interface san-port-channel <channel-id>
%FSPF-3-FC2_PROC_ERR: %$VSAN <vsan-id>%$ Error in processing HELLO  packet on inter
san-port-channel <channel-id>, Error  = Bad packet received
```

VSAN traffic is not being routed through SAN fabric. Which action is helpful to resolve the problem?

A. Make sure that the FSPF hello interval value matches on both switches.

B. Change the FSPF hello timer back to the default of 5 seconds.

C. Make sure that the FSPF hello timers are different so that they do not compete.

D. Make sure that the FSPF dead timers are both set to 0.

Correct Answer: A

QUESTION 2

Which two fields should be examined when you use the show otv overlay command to verify that the overlay interface is enabled and the parameters match on both sides? (Choose two.)

A. VPN name

B. VPN state

C. Control group

D. Data group range

E. Join interface

F. Site VLAN

Correct Answer: BC

QUESTION 3

Refer to the exhibit.

An administrator sets up a FabricPath network. The administrator tries to ping between two SVI interfaces on the leaf switches 10 and 20, but it fails. What caused the pings to fail?

A. Switches S10 and S20 do not have F2 modules.

B. The vPC peer gateway must be enabled on switches S10 and S20.

C. Switches S1, S2, and S3 should be interconnected directly.

D. VLAN 10 is not enabled on the spine switches (S1, S2, and S3).

E. Layer 3 over a vPC+ peer link is not supported.

Correct Answer: D

QUESTION 4

The installation of a new OTV network connecting two data centers via a service provider LAN has failed verification steps. Which statement explains why certain types of data are not being successfully transferred across the OTV network?

A. The number of extended VLANs across all configured overlays may be greater than 256.

B. The number of MAC addresses on either edge device may exceed 4000.

C. The additional 42-byte OTV overhead, along with the DF bit being set, may cause the service provider to drop packets based on their 1500 MTU settings.

D. Having more than two edge devices per site is not supported.

Correct Answer: C

QUESTION 5

Which command can you use to determine if the member ports share the appropriate parameters in order to join a port channel?

A. show port-channel summary

B. show port-channel usage

C. show port-channel compatibility-parameters

D. show port-channel load-balance

Correct Answer: C

Latest 642-980 Dumps   642-980 PDF Dumps   642-980 Exam Questions

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications.
You can view Vendor list of All Certification Exams offered:

https://www.lead4pass.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: