

300-625^{Q&As}

Implementing Cisco Storage Area Networking (DCSAN)

Pass Cisco 300-625 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/300-625.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

Refer to the exhibit.

```
switch-2# show zone status vsan 10
VSAN: 10 default-zone: deny distribute: active only Interop: default
mode: enhanced merge-control: allow
session: cli [admin]
hard-zoning: enabled broadcast: enabled

Default zone:
qos: none broadcast: disabled ronly: disabled
```

A user who is logged in as an operator cannot update the zoneset. What is the cause of this issue?

- A. The fabric is locked by admin on switch-2.
- B. Hard zoning is enabled.
- C. Merge control is disabled.
- D. The switch has a conflicting domain ID.
- E. The fabric is locked by admin on another switch.

Correct Answer: A

QUESTION 2

Which two protocols are used to implement SAN telemetry on Cisco MDS switches? (Choose two.)

- A. RPC transport
- B. GPB transport
- C. gRPC transport
- D. gRPC encoding
- E. GPB encoding

Correct Answer: CE

QUESTION 3

What is the effect of a non-graceful virtual machine shutdown on a virtualized server that is connected to a SAN with Fibre Channel interfaces?

- A. NP Port reload connected to the upstream SAN switch
- B. out-of-service Fibre Channel interfaces on the SAN switch
- C. frames stuck in the storage system
- D. frames stuck in the HBA buffer of the server

Correct Answer: B

QUESTION 4

A storage network engineer must install and configure a new MDS switch in a data center network. Which two statements about available choices during the MDS switch initial setup are correct? (Choose two.)

- A. The engineer can choose what will be the administrator account.
- B. The secure password standard is required.
- C. The engineer can configure the default zone policy.
- D. The engineer can configure the default switch port trunk mode.
- E. The engineer does not have the choice to enable or disable full zoneset distribution.

Correct Answer: AC

QUESTION 5

A storage network engineer is upgrading a Cisco MDS Director with dual supervisor modules. The install command is executed on the standby supervisor module but fails. Which action would have prevented this failure?

- A. All FCoE interfaces configured on the MDS must be shut down before starting the upgrade.
- B. The upgrade must be done on the active supervisor module only.
- C. Cisco Fabric Services must be disabled before starting the upgrade.
- D. Fabric Controller Service must be stopped before starting the upgrade.

Correct Answer: B

[300-625 Practice Test](#)

[300-625 Study Guide](#)

[300-625 Braindumps](#)