

API-571^{Q&As}

Corrosion and Materials Professional

Pass API API-571 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/api-571.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by API Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

SSC is a form of hydrogen stress cracking resulting from the absorption of atomic hydrogen that is produced by the _____ corrosion process on the metal surface.

- A. HCl
- B. HF
- C. Sulfide
- D. Wet H₂S

Correct Answer: C

QUESTION 2

The best way to prevent failures by atmospheric corrosion is to:

- A. Have an aggressive inspection program.
- B. Reduce airborne particulates.
- C. Install and maintain appropriate coatings.
- D. Shoot all birds that cross the plant fence.
- E. Build new petrochemical facilities in a dry desert.

Correct Answer: C

QUESTION 3

Inspection for wet H₂S damage generally focuses on _____ and _____.

- A. Weld seams
- B. Nozzles
- C. Trays
- D. Down comers
- E. A and B

Correct Answer: E

QUESTION 4

Corrosion rates of the anode can be high if there is a _____ anode to cathode ratio.

- A. Large
- B. Small
- C. Severe
- D. None of the above

Correct Answer: B

QUESTION 5

Which of the following materials are generally not suitable for HF service?

- A. 300 Series SS
- B. Carbon steel
- C. 400 Series SS
- D. Both A and C

Correct Answer: D

[API-571 PDF Dumps](#)

[API-571 Study Guide](#)

[API-571 Brainsdumps](#)