

## CQE<sup>Q&As</sup>

Quality Engineer Exam

### Pass ASQ CQE Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/cqe.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by ASQ Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



**QUESTION 1**

The MOST essential value of a surface plate in precision measurement application is which of the following?

- A. It provides a flat working surface.
- B. It provides a surface free of minor vibration.
- C. It provides an accurate reference surface.
- D. It provides a chemically resistant work surface.

Correct Answer: C

---

**QUESTION 2**

The design function which assigns probability of failures between components or subsystems is called

- A. Apportionment.
- B. Significance
- C. Confidence.
- D. Qualification.

Correct Answer: A

---

**QUESTION 3**

The hypergeometric distribution should be used instead of the binomial distribution when

- A. There are more than 2 outcomes on a single trial.
- B. Each trial is independent.
- C. Sampling does not involve replacement.
- D. There is a fixed number of trials.

Correct Answer: C

---

**QUESTION 4**

Which of the following distributions models events that have 2 possibilities on each trial?

- A. Normal.
- B. Poisson.

C. Binomial

D. gamma.

Correct Answer: C

---

## QUESTION 5

Typically Pareto diagrams are used for which of the following reasons?

- . To display the significant few categories.
- . To compliment attribute data charting.
- . To eliminate insignificant categories.
- . To focus attention in priority order.

A. I and III only

B. I, II and III only

C. II, III and IV only

D. I, II, III and IV

Correct Answer: D

[CQE VCE Dumps](#)

[CQE Practice Test](#)

[CQE Exam Questions](#)