

## HPE0-S54<sup>Q&As</sup>

Designing HPE Server Solutions

**Pass HP HPE0-S54 Exam with 100% Guarantee**

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/hpe0-s54.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



**QUESTION 1**

A customer has installed a D3940 storage module in an existing Synergy frame. However, none of the compute modules can access the shared storage.

What is the problem?

- A. The storage module has not been initialized in the composer
- B. There are no SAS modules installed in bays 1 and 4
- C. There are no fibre channel modules installed in bays 1 and 4
- D. The I/O modules have not been initialized in the composer

Correct Answer: B

---

**QUESTION 2**

A customer is using HPE Smart Update Manager (SUM) for firmware update. They plan to add 100 Gen10 ProLiant servers, and they are concerned about whether HPE SUM will be able to support this size of installation.

What other option could the customer use for firmware updates that has increased scalability?

- A. iLO Advanced Premium Security Edition
- B. Insight Control server provisioning
- C. Insight Cluster Management Utility
- D. iLO Amplifier Pack

Correct Answer: D

---

**QUESTION 3**

A customer wants a highly available storage solution inside HPE Synergy that is comparable via OneView and also accessible outside the enclosure to a DR site at another location.

Which product fits the customer's needs?

- A. HPE StoreVirtual VSA
- B. VMware vSAN
- C. SEPH SUSE
- D. HPE 3PAR StoreServ

Correct Answer: A

---

## QUESTION 4

While installing a three frame Synergy solution, only two of the frames are identified during the discovery process.

What should you do to get resolution?

- A. Remove and re-insert the standby Composer
- B. Issue a refresh command to the enclosure
- C. Open the front panel of the Composer, and read the error message
- D. Validate Frame Link Module topology

Correct Answer: D

---

## QUESTION 5

A customer received their three frame Synergy system. However, they are missing a link cable that connects the frame link module between the frames. Which type of cable do they need?

- A. DAC
- B. MPO
- C. CAT6A
- D. AOC

Correct Answer: A

[HPE0-S54 PDF Dumps](#)

[HPE0-S54 Practice Test](#)

[HPE0-S54 Braindumps](#)