

Six Sigma Black Belt Certification - CSSBB

Pass ASQ CSSBB Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.leads4pass.com/cssbb.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by ASQ Official Exam Center

Instant Download After Purchase

100% Money Back Guarantee

😳 365 Days Free Update

Leads4Pass

800,000+ Satisfied Customers



QUESTION 1

Situations where standardized work needs to be incorporated include all of these except

- A. Changeover instructions incomplete
- B. Lack of a system to assure proper inventory levels at repair stations
- C. Machines continually operating to reduce the labor cost per piece
- D. Process flow for the same product assembly taking various cycle time for completion

Correct Answer: C

QUESTION 2

The English words used for the 5S\\'s are Sorting, Straightening, ______, ____, and Sustaining. (Note: There are 2 correct answers).

- A. Shaping
- B. Shining
- C. Standardizing
- D. Signing

Correct Answer: BC

QUESTION 3

A valid Multiple Linear Regression (MLR) is characterized by all of these except ______.

- A. It is an assumption that the X\\'s (inputs) are not correlated to each other
- B. The X\\'s (inputs) are assumed to be independent of each other
- C. MLR is conducted based on a deliberate form of experimentation
- D. The Residuals from MLR analysis have to be Normally Distributed

Correct Answer: C

QUESTION 4

Which Experimental Design typically is most associated with the fewest number of input variables or factors in the design?

A. Response Surface design

- B. Full Factorial design
- C. Simple Linear Regression
- D. Fractional Factorial design

Correct Answer: A

QUESTION 5

Sally and Sara sell flower pots at their garage sale. Sally motivates Sara mentioning that they will sell a minimum of 15 pots per day if the outside temperature exceeds 600 F. From a sample, whose population is assumed to follow a Normal Distribution, taken for 30 days at 60 degrees or more an average of 13.6 pots per day were sold with a Standard Deviation of 0.7 pots. For the sales accomplished above, what test would validate if they met their requirements?

A. F Test

- B. Test for Equal Variance
- C. Chi Square Test
- D. One-Sample t-Test

Correct Answer: D

QUESTION 6

A valid mathematical Regression represents all of the characteristics shown except _____

- A. The residuals when plotted follow a Normal Distribution
- B. The sum of the residuals is zero
- C. All of the standardized residuals will be within ? Standard Deviations
- D. Most standardized residuals are within ? Standard Deviations

Correct Answer: C

QUESTION 7

When doing Hypothesis Testing on Non-normal data Belts will use a ______ to compare more than two sample proportions to each other.

- A. Z score Table
- B. Sakami Table
- C. Mean-to-Mode Analysis
- D. Contingency Table

Correct Answer: C

QUESTION 8

Which statement(s) are incorrect for the Regression Analysis shown here? (Note: There are 2 correct answers).

```
Regression Analysis: Turbine Output versus Air-Fuel Ratio, % steam, ....
The Regression Equation is
TurbineOutput = 16.5 + 3.21 Air-Fuel Ratio + 0.386 % methane
               + 0.0166 SteamExitTemp
                   Coef SE Coef
Predictor
                                      T
                                             P
                          2.918 5.65
0.2377 13.52
                                         0.000
Constant
                 16.488
Air-Fuel Ratio
                 3.2148
                                         0.000
               0.38637
                        0.07278
                                  5.31
                                         0.000
methane
SteamExitTemp 0.016576 0.004273
                                  3.88
                                         0.004
S = 0.508616 R-Sq = 98.6%
                             R-Sq [adj] = 98.2%
Analysis of Variance
Source
               DF
                        SS
                               MS
                                        F
                                               P
               3 170.003 56.668 219.06 0.000
Regression
               9
Residual Error
                   2.328
                            0.259
Total
               12 172.331
Source
               DF
                   Seq SS
Air-Fuel Ratio
                   159.048
                1
                     7.062
% methane
                1
SteamExitTemp
                1
                     3.892
```

A. The air-fuel ratio explains most of the TurbineOutput variation

B. The Regression explains over 98% of the process variation

C. This Multiple Linear Regression has three statistically significant independent variables

D. If the air-fuel ratio increases by 1, the TurbineOutput more than triples

E. The SteamExitTemp explains the most variation of the TurbineOutput

Correct Answer: DE

QUESTION 9

What dollar amount of savings would a project show if it reduced your outstanding Accounts Receivable by \$1.4 million dollars to \$5.3 million total and your organization\\'s marginal cost of capital was 6.2%?

A. \$43,400

B. \$86,800

C. \$117,500

D. \$328,600

Correct Answer: B

QUESTION 10

Control Charts were developed by Dr. Shewhart to track data over time. To detect Special Cause variation the Control Charts use which of these?

- A. Data shift analysis
- B. Outlier analysis methods
- C. Center Line and Control Limits
- D. None of the above

Correct Answer: C

QUESTION 11

The Waste of Overproduction is defined as _____.

- A. The unnecessary movement of people and equipment
- B. The liability of materials that are bought, invested in and not immediately sold or used
- C. Producing more than the next step needs or more than the customer buys
- D. The extra movement of material

Correct Answer: C

QUESTION 12

If the production is for higher volume and monitoring and the Mean and variability is to be monitored for four machines producing product and the characteristic to be monitored is Variable Data, which SPC Chart is best to be selected?

- A. Xbar-R Chart
- B. Individual-MR Chart
- C. NP Chart
- D. CUSUM Chart

Correct Answer: A

QUESTION 13




Which of these are examples of business metrics or Key Performance Indicators commonly referred to as KPI\\'s?

- A. Cycle Time
- B. Defects
- C. No. of Units Reworked
- D. Labor Hours
- E. All of these answers are correct

Correct Answer: E

QUESTION 14

The class score distribution of schools in a metropolitan area is shown here along with an analysis output. Comment on the statistical significance between the Means of the two distributions. Select the most appropriate statement.



A. The two class Means are statistically different from each other

B. The two class Means statistically not different from each other

C. Inadequate information on class Means to make any statistical conclusions

D. A visual comparison shows that class Means are not statistically different

Correct Answer: A

QUESTION 15

Upon completion and validation of an improvement to a process a Belt and the Project Team create a Control Plan that contains which of these?

- A. Standard operating work description of the process change
- B. Description of the monitoring system in place to assure continued compliance
- C. Summary of the targeted critical metrics for process performance measurement
- D. All of the above

Correct Answer: D

Latest CSSBB Dumps

CSSBB PDF Dumps

CSSBB Braindumps