

H35-211^{Q&As}

HCIP-Access V2.5

Pass Huawei H35-211 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/h35-211.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

(single) Is the following description correct?

The MA5600T/MA5680T supports Ethernet, E1, and POTS services on the PON side and does not support ATM services.

- A. True
- B. False

Correct Answer: A

QUESTION 2

(Single-choice) An IPTV user reflects that the TV cannot be watched, open the debug switch on the OLT side, and the debug printing information is as follows: huawei(config).

This can be judged by the results of the query

- A. The poN port multicast bandwidth is insufficient
- B. The user does not have permission to watch the show
- C. IGMP Sakamoto Fussel
- D. User bandwidth validation failed

Correct Answer: D

QUESTION 3

(single) What type of access interface does the ONU have to provide when carrying a TDM signal in a GPON system?

- A. Eth
- B. POTs
- C. E1
- D. STM-1

Correct Answer: C

QUESTION 4

(single) By default, which type of queue scheduling mode is on the MA5600T/MA5680T?

- A. WRR

- B. PQ
- C. WFQ
- D. CQ

Correct Answer: B

QUESTION 5

In the evolution of EPON to 10 G EPON, a smooth transition is achieved at the local level by adding WDM WDM modules, and ODNs coexist

- A. True
- B. False

Correct Answer: B

QUESTION 6

The (radio) device periodically sends and receives LMCP packets to avoid information loss, and if packets are not received during () LACp packet interaction cycles, the system considers the port to be down

- A. 3
- B. 5
- C. 4
- D. 2

Correct Answer: A

QUESTION 7

(single) Is the following description correct?

When negotiating the project acceptance test project with the customer, it is recommended to submit the product related product acceptance manual directly to the customer, and let the customer choose the test project.

- A. True
- B. False

Correct Answer: B

QUESTION 8

(Radio) When the invitation message sent by user A reaches user B after passing through server C, D, E, the message received by user B is VIA. The server address of the field information record is in descending order.

- A. C->D->E
- B. E->C->D
- C. E->D->C
- D. C-E->D

Correct Answer: C

QUESTION 9

(single) Take the MA5600 as an example. If you need to analyze the faulty service and find faults through the performance statistics provided by the MA5600, which of the following commands should be used to query system performance statistics?

- A. huawei(config-if-SCU-0/7)#display port state 0
- B. huawei(config-if-SCU-0/7)#display port statistics 0
- C. huawei(config-if-SCU-0/7)#display port traffic 0
- D. huawei(config-if-SCU-0/7)#display port opticstate all

Correct Answer: B

QUESTION 10

(single) Is the following description correct?

The MA5600T/MA5680T supports traffic shaping for specific service-ports.

- A. True
- B. False

Correct Answer: B

QUESTION 11

(single) For the description of the UA5000, which of the following statements is incorrect?

- A. The UA5000 adopts the same hardware platform and supports PSTN, NGN, IMS and FTTx four networks.
- B. UA5000 various traditional private line services under TDM/PSTN.
- C. The UA5000 supports ADSL2+ service access.

D. The UA5000 does not support VDSL2 service access.

Correct Answer: D

QUESTION 12

(single) What is the smallest constituent unit in the message composition mechanism of the H.248 protocol?

- A. Message message
- B. Transaction transaction
- C. Associate context
- D. Command command

Correct Answer: D

QUESTION 13

(single) Which of the following is the command to check whether the running status of all boards in the MA5600T/MA5600T 0 is normal?

- A. display board 0
- B. display frame info 0
- C. display board info 0
- D. display frame info 0/0

Correct Answer: A

QUESTION 14

(single) encounters VoIP service with other vendors' devices. The ONU's RTP temporary terminal resource range setting is inconsistent with the peer softswitch. Which of the following is the fault description?

- A. The user picks up the phone under the ONU.
- B. Under the ONU, the caller and the called party are not connected.
- C. The ONU makes the caller's off-hook dialing to listen to the busy tone in a random time.
- D. Under the ONU, the user makes the caller off-hook without sound.

Correct Answer: C

QUESTION 15

Multiple) When all users under the ONU device have an off-hook and no sound failure, what are the possible causes of the failure?

- A. The voice file is not loaded on the ONU.
- B. ONU external line or telephone failure
- C. ONU internal line fault
- D. MG interface failure

Correct Answer: ACD

[Latest H35-211 Dumps](#)

[H35-211 Practice Test](#)

[H35-211 Exam Questions](#)