HPE0-S56^{Q&As}

Building HPE Hybrid IT Solutions

Pass HP HPE0-S56 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/hpe0-s56.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.leads4pass.com/hpe0-s56.html 2024 Latest leads4pass HPE0-S56 PDF and VCE dumps Download

QUESTION 1

DRAG DROP

Match each workload profile description with the corresponding profile. (Select all that apply.)

Select and Place:

Profile		Description
Mission Critical		Maximizes processor speed
Transactional Application Processing		Large number of database operations
General Peak Frequency Compute		Trades performance for reliability
Correct Answer:		
Profile	General Peak Frequency Compute	Description Maximizes processor speed

QUESTION 2

You are troubleshooting an HPE ProLiant rack-mount server. You need to run diagnostic tests on local storage. Which HPE tool should you use?

- A. iLO
- B. Intelligent Management Center
- C. Smart Storage Administrator
- D. OneView

Correct Answer: B

Leads4Pass

https://www.leads4pass.com/hpe0-s56.html

2024 Latest leads4pass HPE0-S56 PDF and VCE dumps Download

QUESTION 3

A customer has implemented an HPE ProLiant server with internal storage and needs to monitor the array health status. Which management application can the customer use to discover errors quickly and minimize the possible downtime?

- A. Insight Online
- B. Smart Storage Administrator
- C. Intelligent Management Center
- D. InfoSight

Correct Answer: B

QUESTION 4

A company needs a solution that provides SMB and NFS file shares. The solution must have a built-in data backup to Microsoft Azure. Which HPE solution meets the customer\\'s needs?

- A. StoreOnce 3520
- B. StoreEasy 1000
- C. StoreOnce VSA
- D. StoreVirtual VSA

Correct Answer: B

QUESTION 5

You are installing an HPE ProLiant server that has a shared network port for iLO and NIC teaming. You need to ensure that you can still access iLO after configuring the NIC team. Which teaming technology should you configure?

- A. round robin
- B. switch-assisted load balancing
- C. receive load balancing
- D. network fault tolerance

Correct Answer: D

QUESTION 6

What can you do when installing an HPE switch to provide protection from electrostatic discharge?

A. Install the switch in a rack with rubber insulators.

Leads4Pass

https://www.leads4pass.com/hpe0-s56.html

2024 Latest leads4pass HPE0-S56 PDF and VCE dumps Download

- B. Use a power surge protector.
- C. Load balance the power supplies.
- D. Connect the switch grounding cable correctly.

Correct Answer: D

QUESTION 7

You are installing multiple components into an existing server.

Which HPE resource can you use to verify the compatibility of the server hardware options with the server? (Select two.)

- A. Smart Selling tool
- B. Server User Guide
- C. iQuote Universal
- D. Quickspecs
- E. SPOCK

Correct Answer: BE

QUESTION 8

A customer requires a recovery strategy that provides multiple rollback points during the day for their Microsoft SQL database. The customer needs to be able to recover data instantly. Which method meets this requirement?

- A. offsite log shipping
- B. tape copy
- C. storage replication
- D. snapshot

Correct Answer: D

QUESTION 9

A company plans to purchase new HPE servers. The company needs to maximize local storage capacity within the servers. Which HPE servers should the company install?

- A. ProLiant BL460c Gen10
- B. ProLiant DL380 Gen10



https://www.leads4pass.com/hpe0-s56.html

2024 Latest leads4pass HPE0-S56 PDF and VCE dumps Download

- C. ProLiant ML110 Gen 9
- D. ProLiant DL360 Gen 9

Correct Answer: B

QUESTION 10

You are installing a rack at customer site.

How can you ensure redundant power to the rack?

- A. Install two power distribution units (PDUs) with each one connected to a power socket supplied by an independent electrical power source.
- B. Ensure 3-phase power is available in the data center.
- C. Connect an uninterruptible power supply (UPS) to redundant circuit breakers at the facility power source.
- D. Use two different power cords to connect the server to the power grid at the customer site.

Correct Answer: C

HPE0-S56 VCE Dumps HPE0-S56 Study Guide HPE0-S56 Exam Questions