

H13-341^{Q&As}

Huawei Certified internetwork Expert - Transmission

Pass Huawei H13-341 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/h13-341.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

The maximum output optical power of an OBU board is 20 dBm, when it is used in a C-band 80-channel system	, what is
the standard per-channel output optical power?	

- A. +1dBm
- B. -2dBm
- C. +7dbm
- D. +4dBm

Correct Answer: A

QUESTION 2

If the LED indicator value on the SCC board of the OSN 8800 T32 board is 11, which of the following is the subrack ID?

- A. Slave subrack 2
- B. Slave subrack 1
- C. Slave subrack 17
- D. Slave subrack 11

Correct Answer: C

QUESTION 3

Which of the following protection schemes require the APS protocol?

- A. ODUk SPRing protection
- B. ODUk SNCP
- C. SW SNCP
- D. 1:1 optical line protection

Correct Answer: A

QUESTION 4

Which of the following alarms trigger optical line protection switching?

A. POWER_DIFF_OVER



https://www.leads4pass.com/h13-341.html

2024 Latest leads4pass H13-341 PDF and VCE dumps Download

B. R_LOF

C. MUT_LOS

D. R_LOS

Correct Answer: A

QUESTION 5

Which of the following statements about replacing the SCC board is incorrect?

A. In the case of the 1+1 hot backup of the SCC board, replacing the control board does not affect services when the active/standby switchover is performed.

B. After the SCC board is removed, the BD_STATUS and COMMUN_FAIL alarms are reported. After the new board goes online, these alarms need to be manually cleared.

C. If the software version of the new SCC board is later than equipment version, clear the database of the SCC board, and then downgrade the software on the SCC board to the same version as the equipment.

D. If the software version of the new SCC board is earlier than the equipment version, upgrade the software on the SCC board to the same version as the equipment.

Correct Answer: C

Latest H13-341 Dumps

H13-341 Practice Test

H13-341 Study Guide