

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/hp2-t23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

A customer has a ProLiant DL32Ce Gen8 server with a Smart Array B120i controller installed. The customer wants to migrate from RAID 5 to RAID 6 for increased fault tolerance. RAID 6 is not listed as an option in the ACU.

What is the most likely reason that RAID 6 is not an option?

- A. The Smart Array B120i controller does not offer RAID 6
- B. The controller firmware must be upgraded
- C. The Smart Array Advanced Pack must be purchased
- D. The Smart Array BIOS is configured incorrectly

Correct Answer: A

QUESTION 2

A customer lost the password information for the Onboard Administrator of a C7000 enclosure and asks you to restore administrator access.

How should you do this?

- A. Connect to the serial port of the Onboard Administrator and press the reset button to restore the default password.
- B. Use HP SUM in Recovery mode.
- C. Run the Onboard Administrator Recover option from one of the server blades in the enclosure.
- D. Run Remote Insight Board Command Language (RIBCL) from the Insight Display.

Correct Answer: A

QUESTION 3

What should you use to update firmware on several HP VC Ethernet or Fibre Channel modules simultaneously?

- A. Onboard Administrator (OA)
- B. Virtual Connect Manager (VCM)
- C. BladeSystem Firmware Deployment Tool (FDT)
- D. Virtual Connect Support Utility (VCSU)

Correct Answer: D

QUESTION 4

In which direction does the air flow through a c7000 enclosure?

- A. top to bottom
- B. bottom to top
- C. back to front
- D. front to back

Correct Answer: D

QUESTION 5

Which HP utility can patch a ProLiant server with a release set made up of drivers, firmware, and software that have been tested together?

- A. HP Smart Update Firmware DVD
- B. HP Version Control Update (VCU)
- C. Integrated Lights Out (iLO)
- D. Service Pack for ProLiant (SPP)

Correct Answer: D

[HP2-T23 PDF Dumps](#)

[HP2-T23 VCE Dumps](#)

[HP2-T23 Braindumps](#)