

Designing HPE Server Solutions

Pass HP HPE0-S54 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.leads4pass.com/hpe0-s54.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

Instant Download After Purchase

100% Money Back Guarantee

😳 365 Days Free Update

Leads4Pass

800,000+ Satisfied Customers



Leads4Pass

QUESTION 1

Your customer is interested in Synergy and composable infrastructure. They are concerned that operational savings may not meet expectations since operating system installation consumes a great deal of time. Which feature should you highlight to overcome the objection?

- A. The Synergy Composer provides HTTPS boot services
- B. The Synergy Frame Link modules provide PIXE operating boot partitions
- C. The Synergy Composer can provision operating systems in seconds
- D. The Synergy Image Streamer can provision operating systems in seconds

Correct Answer: D

QUESTION 2

What must a customer consider when adding a connection to a Server Profile Template? (Select two.)

- A. Server Profiles will automatically be refreshed
- B. The associated Servers will need to be rebooted
- C. Additional Server Profiles will need to be created
- D. The associated Server Profiles will be flagged as inconsistent
- E. Server Profiles will need to be updated from the template

Correct Answer: ABE

QUESTION 3

A customer is purchasing a large number of servers for a business critical application. They are concerned about return to service times and want immediate assistance with critical events. Which HPE service meets the customer\\'s needs?

- A. HPE Proactive Service Credits
- B. HPE Proactive Care Advanced
- C. HPE Proactive Care
- D. HPE Foundation Care

Correct Answer: C

QUESTION 4

Leads4Pass https://www.leads4pass.com/hpe0-s54.html 2024 Latest leads4pass HPE0-S54 PDF and VCE dumps Download

One of the DL380 Gen10 servers in your infrastructure has failed to boot after a 3rd party PCIe NIC was installed.

What is the most likely cause of this issue?

A. HPE does not allow 3rd party PCIe cards.

- B. The latest Support pack for ProLiant must be used before accessing any additional 3rd party products in the server.
- C. The manufacturer did not digitally sign the correct firmware and HPE Secure Boot halted the process.
- D. The iLO interface did not have a correct IP address provided from DHCP.

Correct Answer: C

QUESTION 5

You need to consolidate multiple BOMs, power requirements, and changing criteria of a Converged System due to the review of multiple reference architectures on Microsoft Exchange Server 2016. Which tool should you use?

- A. HPE Sizer for Microsoft Exchange Server 2016
- B. HPE Converged Infrastructure Solution Sizer Suite
- C. HPE Sizer for Server Virtualization
- D. Single Point of Connectivity Knowledge (SPOCK)

Correct Answer: A

HPE0-S54 VCE Dumps

HPE0-S54 Practice Test

HPE0-S54 Braindumps