

ISS-003^{Q&As}

Intel Server Specialist Certification Exam

Pass CompTIA ISS-003 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.leads4pass.com/iss-003.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

Your customer calls you as their preferred Intel Server Specialist to say that a server has suffered a stop error, and intermittently fails to boot. Which of the following is the preferred FIRST step to take?

- A. Ask the customer to return the server.
- B. Start a remote desktop session to the server.
- C. Ask the customer to reseat the memory.
- D. Gather more information about the error. Connect to the remote management module if present.

Correct Answer: D

QUESTION 2

A standard System Event Log record contains: Byte 1-2: Record ID Byte 3: Record Type Byte 4-7: Timestamp Byte 8-9: Generator ID Byte 10: Event Format Revision Byte 11: Sensor Type Byte 12: Sensor Number Byte 13: Event Direction / Type Byte 14: Event Data 1 Byte 15: Event Data 2 Byte 16: Event Data 3

- A. True
- B. False

Correct Answer: A

QUESTION 3

A customer wants to buy an Intel server system in a 1U rack chassis for a web server with Intel Intelligent Node Manager support. Which of the following systems support this feature?

- A. The Intel Server System P4308RPLSHDR
- B. The Intel Server System R1304RPSSFBN
- C. The Intel Server System R1304BTSSFAN
- D. The Intel Server System P4304BTSSFBN

Correct Answer: B

QUESTION 4

A customer has an Intel® Server System R2308WTTY5 based on two Intel® Xeon® E5-2630L v3 processors. The customer tries to power on a virtual machine in Microsoft Hyper-V Manager but gets an error: "The virtual machine could not be started because the hypervisor is not running. Verify that the processor of the physical computer has a supported version of hardware-assisted virtualisation". Which of the following statements explains this case?

- A. The BIOS version of the system is less than R01.01.0008.
- B. Intel® Virtualization Technology is disabled in the BIOS.
- C. Hypervisor reinstallation is required.
- D. Intel® Xeon® E5-2630L v3 processor does not support virtualization technology.

Correct Answer: B

QUESTION 5

Which of the following components can be added to the Intel Server System R2208WTTYS with the RMS3CC080 to improve the RELIABILITY of the system? (Select ALL that apply).

- A. AXXRMM4R
- B. A2U8X25DPDK
- C. AXXRMFBU5
- D. A2UBKTMFBUSSD
- E. AXX1100PCRPS

Correct Answer: CE

[ISS-003 VCE Dumps](#)

[ISS-003 Study Guide](#)

[ISS-003 Exam Questions](#)